



Respiratory Ventilation

20 April 2017

FSN 86600037A

**URGENT - Field Safety Notice
Medical Device Correction
V60 VENTILATORS MANUFACTURED BEFORE 15 SEPTEMBER 2015
INTERNAL CABLE REPLACEMENT**

Dear Customer,

Our records show that you purchased a Philips V60 Ventilator in the past.

Respironics California, LLC ("Respironics") is voluntarily initiating a Correction for all Philips V60 Noninvasive Ventilators (NIV) manufactured before 15 September 2015, which involves replacing an internal cable within the ventilator.

Respironics began distributing V60 Ventilators in 2009. All V60s with date of manufacture before 15 September 2015 are subject to this correction.

V60 Ventilators manufactured on or after 15 September 2015 incorporate a different internal cable and, therefore, are not included in this Correction and no action is required for them.

This document contains important information for the continued safe and proper use of your equipment

Please review the following information with all members of your staff who need to be aware of the contents of this communication. It is important to understand the implications of this communication.

Please retain a copy with the equipment Instruction for Use.

The date of manufacture is visible on the back of the V60 ventilators, so it is unnecessary to pause or discontinue the use of the ventilator to check it.

Please refer to the instructions attached to this letter to determine the date of manufacture of your V60 ventilators.



This notice has been reported to the appropriate Regulatory Agencies. Philips apologizes for any inconveniences caused by this problem.

Sincerely,

Donald J. Sherratt
Head of Quality and Regulatory, Hospital Respiratory Care

URGENT - Field Safety Notice Medical Device Correction

PHILIPS V60 VENTILATORS MANUFACTURED BEFORE 15 SEPTEMBER 2015 – INTERNAL CABLE REPLACEMENT

<p>AFFECTED PRODUCTS</p>	<p>All V60 Ventilators with a date of manufacture before 15 September 2015.</p> 
<p>PROBLEM DESCRIPTION</p>	<p>Over time, low-frequency vibrations can cause the pins within the female connectors on the internal Motor Controller to Data Acquisition Board ribbon cable to become partially displaced, which causes momentary high resistance that interferes with data transfer. This may cause the ventilator to fail Power on Self Testing (POST) or cause Continuous Built in Test (CBIT) to detect a fault and lead to a ventilator shut down with alarm during use or during intra-hospital transport.</p> <p>If the V60 shuts down for any Vent Inop condition and is operating on battery power, an audible high-priority alarm will sound continuously for at least 2 minutes. If the V60 is connected to AC power (mains supply), the alarm will continue to sound until an operator intervenes. If the V60 is connected to a remote alarm system, the alarm system will be activated until action is taken by the operator.</p> <p>The device may display an error code 100A, 1006, 1007, or 1008 on the screen. Displaying one of these error codes indicates that the ventilator has had a communication failure that may be caused by the cable.</p>
<p>HAZARD INVOLVED</p>	<p>If a Vent Inop event occurs when a patient is connected, pressure support and O₂ delivery will cease. Such cessation may cause the patient's SpO₂ to drop and, if the alarm is not attended to promptly, may lead to Hypoxemia or Hypercarbia.</p>
<p>HOW TO FIND THE DATE OF MANUFACTURE OF A V60 VENTILATOR</p>	 <p>The image shows the back panel of a Philips V60 ventilator. Three labels are highlighted with arrows: 'Serial Number' pointing to a circular label on the left, 'Catalog/REF Number' pointing to a rectangular label in the center, and 'Date of Manufacture' pointing to a rectangular label on the right. Below these labels are various ports including a USB port and an RS-232 port. A service label with a barcode and 'SERVICE #' is also visible on the left side.</p>

URGENT - Field Safety Notice Medical Device Correction

PHILIPS V60 VENTILATORS MANUFACTURED BEFORE 15 SEPTEMBER 2015 – INTERNAL CABLE REPLACEMENT

<p>ACTION TO BE TAKEN BY CUSTOMER / USER</p>	<p>If you have checked the date of manufacture and your V60 ventilator is subject to this correction:</p> <ol style="list-style-type: none">1. Continue using the V60. The incidence of failure is low.2. To minimize risks of illness or injury, operate the V60 as directed or recommended in the operator's manual, including by<ol style="list-style-type: none">a. Promptly attending to all alarms presented by the V60 Ventilator.b. Using an external O₂ monitor/analyzer and setting the alarm thresholds appropriately.c. Ensuring the correct circuits and masks identified in the operator's manual are used with the V60.d. Wherever possible, connecting the V60 to a remote call system.3. If the V60 Shuts down, alarms, and displays any of the error codes 100A, 1006, 1007, or 1008, then (i) turn the V60 off, (ii) discontinue use of the V60, and (iii) use an alternate ventilator. Call your local customer service contact and report the failure. Please reference FCO86600037A.4. <i>You must acknowledge receiving this notification by either:</i> <div style="text-align: center;"> </div> <p>Please return to: michael.turvey@philips.com or Fax to 01483 369 037 or Mail to: Michael Turvey, Q&R, Philips Health Systems, Philips, Guildford Business Park, Guildford, Surrey, GU2 8XG</p>
---	---



Respiratory Ventilation

20 April 2017

FSN 86600037A

**URGENT - Field Safety Notice
Medical Device Correction**

**PHILIPS V60 VENTILATORS MANUFACTURED BEFORE 15 SEPTEMBER 2015 –
INTERNAL CABLE REPLACEMENT**

ACTIONS PLANNED BY PHILIPS	Philips will arrange for a Philips Field Service Engineer or Approved Service Provider to install new cables in affected V60 ventilators at no cost to the customer. Philips will contact each consignee to schedule an appointment for this service.
FURTHER INFORMATION AND SUPPORT	Contact information: Monday through Friday between 8:00am and 5:00 pm US Pacific Time Firm responsible for FSN: Respironics California, LLC 2271 Cosmos Court Carlsbad, CA 92011 Local Contact <u>For any further questions, please contact your local Philips representative or the UK Philips Customer Care Service Centre on 0870 532 9741.</u>



Effective 20 April 2016

FSN 86600037A

MEDICAL DEVICE FIELD SAFETY NOTICE RESPONSE PHILIPS V60 MANUFACTURED BEFORE 15 SEPTEMBER 2015 – MC-DA CABLE REPLACEMENT

Acknowledgement and Receipt Form Response is Required

Customer Information:

Customer Name:							
Street Address:							
City:		State:		Zip Code:		Country:	
Contact Person:		Telephone Number:		E-mail:			

I have read and understand the recall instructions provided in the notification letter. Yes No

Have any adverse events associated with recalled product occurred at your site? Yes No

If yes, have you informed Philips of the event? Yes No

If yes, please provide Philips Case Number _____ and details:

Details:

Please return to: michael.turvey@philips.com or Fax to 01483 369 037 or
Mail to: Michael Turvey, Q&R, Philips Health Systems, Philips, Guildford Business Park, Guildford,
Surrey, GU2 8XG

